

Fig 1A
1/13




Fig 1B
2/13




FIG. 1 is a schematic diagram of a circular structure. It features a large outer circle (12) and a smaller inner circle (14). Between these circles are several smaller circles (16) and a central circle (18). The diagram is divided into four quadrants by a vertical dashed line and a horizontal dashed line. The top-left quadrant contains a solid black circle (12). The top-right quadrant contains a circle (18) with a plus sign (+). The bottom-left quadrant contains a circle (18) with a plus sign (+). The bottom-right quadrant contains a circle (18) with a plus sign (+). The central circle (14) also contains a plus sign (+). The label E1 is positioned at the top center, with a horizontal line and arrows pointing left and right.





Fig 1D
4/13






Fig 2B

Fig 2C

Fig 2A
6/13




Fig 3A
7/13




Fig 3B
8/13




Fig 4A
9/13




Fig 4B
10/13




Fig 5
11/13







Fig 7
13/13



**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ BLACK BORDERS
- ☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
- ☒ FADED TEXT OR DRAWING
- ☒ BLURRED OR ILLEGIBLE TEXT OR DRAWING
- ☐ SKEWED/SLANTED IMAGES
- ☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
- ☐ GRAY SCALE DOCUMENTS
- ☒ LINES OR MARKS ON ORIGINAL DOCUMENT
- ☒ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
- ☐ OTHER: _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.